Test Report



Customer

Alu Rehab

Test Item

Netti III Mini

Test

ISO 7176-19:2008 as amended by EN

12183:2014

Millbrook Report No.

15/1024

Millbrook Test No.

S13864

Author:

B. Appleyard Engineer

Approved:

S. Jones

Principal Engineer

Date:

25th November 2015





Test Results Summary

Test No:	S13864	
Test Type	ISO 7176-19:2008 as amended by EN12183:2014	
Manufacturer	Alu Rehab.	
WC Model:	Netti III Mini	ľ
Mass:	28.5kg	
Seat Rail Angle:	18.5°	
Seat Back Angle:	66°	RESULTS
Head Restraint:	Fitted	
Occupant:	Hybrid II 5 th Percentile (52kg)	
Front Tie Downs:	Unwin OF03	
Rear Tie Downs:	Unwin OR02	
Occupant Restraint:	MPG SORv1	
5.1 During the Test		
a) Horizontal ATD an	d wheelchair excursion limits as per limits shown in Table 3:-	
Was the horizonta	I movement of the test wheelchair P- Point (X _{ss}) less than 200	Pass
mm. (±5 mm)		15mm
mm)	I movement of the dummy Knee (X _{knee}) less than 375 mm. (±5	Pass 167mm
Was the forward h	orizontal movement of the Dummy Head (XheadF) less than 550	Pass
mm. (±5 mm)		367mm
Was the rearwards horizontal movement of the Dummy Head (XheadR) greater than		Pass
-450 mm. (±5 mm)	-	226mm
b) Was the ratio X _{knee}	/X _{ss} >1.1:1	PASS 11:1
	f powered wheelchairs, or their surrogate parts:-	
move outside of the wheelchair footprint		N/A
II. move into the	wheelchair user's space	N/A
5.2 Post Test		
 a) Did the wheelchair remain upright on the test platform and did the ATD remain in a seated posture in the test wheelchair with a torso angle > 45° 		Pass
b) Did the wheelchair securement points show visible signs of material failure		Pass
c) Did any component wheelchair	ts of a mass greater that 100g become detached from the	Pass
d) Did any occupant o less than 2mm	contactable components fragment or separate with an edge of	Pass
e) Did any primary load carrying components of the wheelchair show any visible signs of failure		Pass
f) Did any 'tilt in space' locking mechanisms show signs of failure		Pass
g) Was the ATD released from the wheelchair without the use of tools		Pass
h) Was the wheelchair released from the restraint system without the use of tools		Pass
	ecrease of H-Point height relative to the wheelchair platform	Pass 1%
j) Did the wheelchair	and its components cause partial or complete failure of the he WTORS assemblies	Pass
The wheelchair met the dynamic test requirements of ISO 7176-19:2008 as amended by EN12183:2014		